

100




Figure 1
(Prior Art)




Figure 2A
(Prior Art)




Figure 2B
(Prior Art)

00727-9094E260




Figure 3

400




Figure 4A

0373606-12400




Figure 4B





Figure 4C

004T 2T 9092E 60

500a



500b




Figure 5

510







Figure 6A



THE CENTER OF THE RESIST
RECTANGLES WILL REMAIN COINCIDENT
WITH THE CENTER OF THE SHOT

Figure 6B

CW ROTATION ABOUT THE LEFT
CENTER OF THE SHOT.



THE CENTER LOCATION OF THE
RESIST RECTANGLE "FALLS" IN BETWEEN
THE CENTER OF THE SHOT AND THE
CENTER OF WHERE THE RIGHT RECTANGLE
"LANDED", SO THE ERROR IS CUT BY Y_2 .

Figure 6C

700




Figure 7

097606.12400

830




Figure 8